
REPAIR WANUAL

35 ED

CONTENTS


	Page
DRAWING AND PARTS LIST	1
FEATURE OF MECHANISM	10
INSPECTION STANDARD	11
DISASSEMBLY PROCEDURE	18
TROUBLESHOOTING	26
LIST OF LUBRICANTS AND CHEMICALS	57



DRAWING AND PARTS LIST


EXPLANATORY NOTES ON VARIOUS MARKS & NUMBERS USED IN IMPROVED PARTS TABLE


×	Only Body Die-Cast is not available in case of overseas.
0	An assembled parts is supplied including parts marked with
1	Single parts is supplied.
()	Not to be supplied in single parts, but as an assembled parts.
O	Left-handed screw, (the mate screw hole is not marked particularly). All right-handed screws have no special indication.
< >	Improved parts. Number shows INDEX in IMPROVED PARTS TABLE where more details are explained.
===	No more available parts.
<i>277</i>	The place where parts have been improved.
{ }	Dimensions of improved parts and improved points.
$\gamma \diamondsuit $ \Leftrightarrow	Replacing parts of no more available parts marked with =
*	How to replace parts or how to repair.
	Original parts are also usable instead of improved parts.
\times	Printing'error. No parts are built-in cameras.
	Clarify HOUSE CODE, PARTS NUMBER and QUANTITY in your ORDER SHEETS.



JAL		
HOUSE CODE		
LEE-17	FIG. 1/4	
OLYMPUS OPTICAL CO, LTD. TOKYO. JAPAN		
	HOUSE CODE	


NOTE: WHEN ORDERING FOR SPARE PARTS, PLEASE CLARIFY A MODEL, PARTS NUMBER AND QUANTITY






REPAIR MANUA	\L	
MODEL	HOUSE CODE	
OLYMPUS 35 ED	LEE-17	FIG, 3/4
OLYMPUS OPTICAL CO., LTD. TOKYO. JAPAN		

NOTE: WHEN ORDERING FOR SPARE PARTS, PLEASE CLARIFY A MODEL, PARTS NUMBER AND QUANTITY





REPAIR MANUAL		
MODEL	HOUSE CODE]
OLYMPUS 35 ED	LEE-I7	FIG. 4/4
OLYMPUS OPTICAL CO., LTD. TOKYO. JAPAN		

NOTE: WHEN ORDERING FOR SPARE PARTS, PLEASE CLARIFY A MODEL, PARTS NUMBER AND QUANTITY

	· *	
PARTS NO.	NAME OF PARTS.	NOTE
CA 5258	SYNCHRO SOCKET TERMINAL	4 parts 4 kinds
5259	SYNCHRO SOCKET	
5263	SYNCHRO CONTACT POINT	
5441	SPOOL SPRING	
5509	CLUTCH SPRING	
5526	SPOOL HOLDER	
5527	C WASHER	
5709	E RING 3	
5765	COVER	· · · · · · · · · · · · · · · · · · ·
5949	SP GEAR SCREW	,
6008		
6084	HINGE PIN	
· ·	LEAD COIL C	
65.90	KEY SPRING	
6970	LIGHT PROOF PADDING	
6977	KEY GUIDE	
, 7156	COIL COVERING TUBE	
7315	LIGHT PROOF PADDING	
7329	STOPPER SPRING	
7334	R LEVER	3 parts 3 kinds
7335	R PINCH	
7336	R PINCH SHAFT	
7338	FRICTION SPRING	· .
7341ъ	SHOE CONTACT POINT	3 parts , 3 kinds
7399	LEVER HOLDER	•
7460	MIRROR BASE SPRING	· •
7486	LIGHT PROOF PADDING	
7529	SPOOL A	1
7559	RNUT	
7612	L WINDOW	
7712	CONTACT POINT	
7714	B PLATE	
7718	HINGE	
7721	STOPPER SCREW	·
7732	FILM GUIDE	
7921	STOPPER SCREW	
8008	P HOLDER	
8025	R SHAFT	
8038	SCREW GEAR	
8072	LIGHT PROOF PADDING	
8095	RING HOLDER	1
8102	M SPRING	1
8103	AD SCREW	1
8106	COVERING SCREW	
8110	MIRROR HOLDER	
8120	R SCREW	
8174	SYNCHRO TERMINAL NUT	· ·
8222	PRESSURE PLATE	4 parts 3 kinds
8225	FILM WINDING LEVER	2 parts 2 kinds
8227	FW SHAFT	2 pares 2 killus
8228	FW LEVER COVER	1
8230	FW PLATE	3 parts 3 kinds
8231a	FW LEVER WASHER a	t: 0.1
8231b		_
8231 c	FW LEVER WASHER b	1
	FW LEVER WASHER C	t: 0.6
8232	FW SPRING	

- 6 -

PARTS NO.	NAME OF PARTS	NOTE
CA 8233	GEAR NO.1 WASHER	
8237	GEAR NO.1	
8242	GEAR NO.1 SHAFT	
8 2 44	SPROCKET	2 parts 2 kinds
8245	SP GEAR	
8252	FC GEAR	ļ
8254	FC PLATE	
8255	FRICTION RING	
8257	K IDLE 1	
8258	K IDLE 2	1
8262	RETURNING SPRING 1	
8265	CLUTCH	
8268	FC WINDOW	
8271	SP LOWER HOLDER	
8272	R BUTTON	
8273	R SHAFT HOLDER	
8276	SHOE SPRING	
8313	REAR COVER LEATHER	
8317	EYE PIECE FRAME	
8322	LIGHT PROOF PADDING	
8326	SHOE BASE PLATE	
8327	S CONTACT POINT	
8329	FRAME HOLDER	
8341	BUTTON SPRING	
8356	HOOK	
8804	E RING	٠. ا
CC 1001	(CAMERA BODY)	Not available
1003	LIGHT PROOF FRAME	3 parts 3 kinds
1006	BOTTOM PLATE	,
1007	VIEW FINDER HOUSING	32 parts 32 kinds
1009	M LEVER	-
1010	FOCUS PIN	
1011	B CASE	7 parts 5 kinds
1012	BATTERY COMPARIMENT LID	
1014	B SPRING	
1015	OB FRAME	
1020	FM FILTER	
1021	FM PLATE	8 parts 7 kinds
1024	STRAP EYELET	· •
1.026	L GUIDE	
1028	SELF TIMER SET LEVER	2 parts 2 kinds
1029	LEVER SET SCREW	
1030	L WINDOW	1
1032	KEY PLATE A	
1033	KEY COVER	1
1034	RIGHT SIDE LEATHER	
1035	LEFT SIDE LEATHER	
1036	SHUTTER RELEASE BUTTON	
1037	SHOE	J
1038	BUTTON WASHER	
1039	LENS HOUSE	3 parts 3 kinds
1040	LEAD COIL	68mm long, Red
1041	FRONT LENS HOLDER	John Tong, Red
1042	HELICOID	2 parts 2 kinds
	·	2 parts 2 killus

		<u> </u>
PARTS NO.	NAME OF PARTS	NOTE
CC 1044	GN RING	·
1.045	FOCUS RING	
1046	MOUNT RING	·
1047	HELICOID GUIDE	
1048	LEAD COIL	30mm long, black
1049	C SCREW	
1050	S LOWER HOLDER	
1051	OBJECTIVE FRAME	
1053	FW BASE PLATE	2 parts 2 kinds
1054	A LEVER	3 parts 3 kinds
1056	SCREW NO.1	_
1057	SPRING NO.1	j
1059	LEVER NO. 2	2 parts 2 kinds
1060	COLLAR NO. 2	·
1061	SCREW NO.2 A	-
, 1062	SPRING NO.2	İ
1065	SCREW NO.3	
1066	SPRING NO.3	
1067	LEVER NO.3	2 parts 2 kinds
1069	CLAW SCREW	1
1070	STOPPER	
1071	SCREW NO.4	
1072	SPRING NO.4	
1073	GEAR CHECKING CLAW	
1074	COLLAR NO.5	•
1075	SPRING NO.5	
1076	CAM PLATE	<u> </u>
1077	S GEAR	
1078	S GEAR SHAFT	_
1080	GEAR NO. 2	2 parts 2 kinds
1081	FC BASE PLATE	18 parts 17 kinds
1082	SP. UPPER HOLDER	
1083	SP SHAFT	
1110	LIGHT PROOF PADDING	
1113	REAR COVER	10 parts 10 kinds
1115	C RING	
1120	R KNOB	
LC 4052	HALF MIRROR	
4067	COVER GLASS	
4075	MIRROR NO.2	
6116	LENS NO.1	
6117	LENS NO.2	
6120	OBJECTIVE NO.1	
6121	EYE PIECE LENS	
6123	MAGNIFIER	4 parts 4 kinds
61.24	VIEW FIELD FRAME	
6125	MIRROR NO.1.	
CB 2101	FILM ROLLER	
2111	SPRING NO.1	· ·
2112	LEAD COIL	50mm long, Black
2160	TOP COVER	18 parts 18 kinds
2162	FW PLATE SPRING	TO FORGE NO INTIMO
2163	SP SPRING	·

- 8 -

PARTS NO.	NAME OF PARTS	NOTE
CB 2164 2165 2166 2167 2168 2170 2172 2173	F BASE PLATE LEVER NO.1 F PLATE L WINDOW FRAME SCREW NO.2 B LEVER NO.1 SHAFT MIRROR SCREW F COVER	4 parts 3 kinds 2 parts 2 kinds 8 parts 8 kinds
ESFB	SHUTTER ASS'Y	
	SET SCREW PUK 1.7 x 2 : SO	
,	1.7 x 2.5 SO 1.7 - 308 SO 2 x 3 SO 2 x 3 SA 2 - 240 SO 2 - 338 SO	
	3PUK 1.4 x 2.2 SO	
	HK 1.7 x 8 SN	
	NW 1.5 - 350 BO 3.8 - 2120 BO 6.1 - 392 BO	
	PSK 1.7 x 2.2 SO 2 x 2.5 SO 2 x 2.5 SA 2 x 3 SO 2 x 4 SO	
·	3PSK 2 x 4 SO	

Outline and Main Performance of the Product

Product Name OLYMPUS 35ED

Model Name LEE-17

Picture Size: 24 x 36mm

Lens: D. Zuiko F2.8 f=38mm (4 elements in 3 groups, Tessar type)

Picture Angle: 60°

Shutter: SEIKO ESF-B (electronic shutter)

4-1/800 sec., 1/30 sec. at flash shooting (Flash iris diaphragm: F2.8-22)

Synchronization: X contact

Guide Number: 10, 14, 20, 28, 40 (m) 32, 45, 65, 90, 130 (ft)

Finder: Bright frame finder. 0.55 magnification, Parallax correction mark,

Battery checker/shutter operation checker (yellow lamp or green lamp
at flash - lights up to indicate normal function)

Film Winding: Lever type one-stroke winding, Preparatory angle 35°, Winding angle 135°, Multiple-stroke winding available, Double winding prevention, Double exposure prevention

Frame Counter: Forward counting, Automatic return

Film Rewinding: Crank rewinding, Sprocket release button

Focusing: Double image coincidence range finder, Rotary helicoid, Distance scale $0.9m \sim \infty$ (3ft $-\infty$), Effective base length 17mm

Flash Adjustment: Automatically switched to flashmatic setting when electronic flash is mounted on the hot shoe.

Exposure Adjustment: F2.8 4 sec. - F13 1/800 sec., stepless program with electronic shutter

Light Sensor: Point-eye CdS, Receiving angle approx. 50°

Power Supply: Mercury cell JIS HM-N 1.4V 2 pcs.

Film Sensitivity Scale: ASA25 - 800 (DIN15 - 30)

Self-timer: Lever type 85° Approx. 10 sec. delay action

Rear Cover Opening: Hinge type

Hood: 45ϕ Fit-on type (common with 35RC, 35ECR, Pen EED)

Filter Mounting: 43.5ϕ p=0.5 Screw-in type

Dimensions and Weight: 114(W) x 71(H) x 51(D) mm, 415g

LEE-17

Inspection Standard

No.	Item	Description	Remarks
1	Distance scale	<pre>(in meters) 0.9. 1, 1.5, 2, 3, 5m, ∞ (white) (in feet) 3, 4, 5, 7, 15ft (fluorescent orange-yellow)</pre>	
2	Operation of distance ring	Operates smoothly without considerable rough, uneveness, squeak and backlash sounding no strange noise. Operation load is 100 - 400gcm.	
3	Accordance of scale graduation Displacement of ~ mark	The displacement from the index center is within 1/4 of the ∞ mark.	
	Displacement of GNO mark	The circle of the mark is not out of the index line center.	
	Displacement of ASA numerals	Not cut by the ASA indication window at the click stops.	ASA 100
	Displacement of the frame letter S (start)	The index center is not displaced more than 1/4 from the center of the letter S. Check with the rear cover closed.	5 4 5 4 4

No.	Item	Description	Remarks
4	Click of ASA	Surely click stops without considerable backlash.	
. 5	Operation of ASA ring	Operates smoothly without considerable rough and squeak.	
6	Load of ASA	200 - 700gcm	
7	Indication of No.1 in the frame counter	Indicates "1" at the third frame after the winding from the S mark (fourth frame seldom available).	
8	End position of the frame counter	Not advances to 37 - 39 (assumed number) passing over 36.	
9	Return of the frame counter	Surely returns near to the S mark even when the rear cover is quietly opened.	
10	Backlash of the release button	There is not considerable back- lash in the longitudinal and lateral directions. The vertical play is less than 0.2.	
11	Effective height of the release button	1.1 ± 0.4mm from the button seat The allowance after the effective release is more than 0.3mm.	
12	Assurance of the release lock	The release lock position is 0.7mm higher than the release effective height.	Surely locked when the battery is consumed or loaded upside down.

No.	Item	Description	Remarks
13	Two-step release (double wind- ing prevention release and shutter release)	The tolerance limit at which the release of the wind-up prevention mechanism (wind-up becomes available) is made earlier than the effective shutter release is indicated as (-). The release button operation load is less than 600g.	Earlier release (-) V -0.05 Shutter release (0) Later release (+)
14	Operation of the wind-up lever	There is not abnormally heavy resistance, desirably less than 1200g in the film loaded condition.	
15	Assurance of double winding prevention	The next winding should not be available unless the shutter has been released. However, the winding is possible while the release button is depressed.	
16	Release of the wind-up pre-vention	The next winding should be available when the shutter has been released.	·
17	Release on the halfway wind-ing	Impossible. However, possible just before the completion of the winding.	
18	Inclination of the bright frame	Not outstanding.	
19	Indication of lamps	Seen simultaneously with the brigh frame upon lighting. The lamp lights up when the release button is depressed by 0.5 from the button's free position.	t

No.	Item	Description	Remarks
20	Voltage Accu- racy of the battery checker	Lights up at 2.20V, but not at 1.80V	
21	Displacement of range finder	o Lateral displacement: Within 1'00". o Vertical displacement: Within 1'30". o Image displacement at both ends of the range finder window: Within 1'30".	
22	Parallax of the range finder	Not outstanding.	
23	Flare and ghost in the range finder	Not outstanding.	
24	Image cut-off in the range finder window	None.	
25	Position of the sprocket	The sprocket tooth position is 12° - 32° as in the right illustration (measured with the backlash of the sprocket is put aside on the film rail surface side in the wound-up condition)	12°-32° Film rail surface
26	Operation of the sprocket	Not make idle rotation with the R button not depressed. Rotates	

No.	Item _.	Description	Remarks
		smoothly without grating and friction when the R button is depressed.	
27	Assurance of the R button operation	For the one with free position of 0 - 0.4mm, the clutch is surely effected even when the R button is pushed 1mm from flush level of the baseplate. For the one with free position of more than 0.4mm, the clutch hook extent is more than 0.8mm.	
28	Free position of the R button	At the free position, the R button should not project more than 0.2mm from the flush level of the baseplate.	
29	Assurance of the R button returning	When the R button is depressed to the bottom, it should not enter exceeding the concave surface of the baseplate. Surely returns during two frames of the next winding.	
30	Spool rotary force	Rotates smoothly without considerable uneveness with the standard rotary force of (180 - 350) x 6gmm.	
31	Operation of the R knob	Rotates smoothly without considerable resistance and squeak. The returning extent of the R shaft is not considerable when the R lever is released in the middle of the winding.	

No.	Item	Description	Remarks
32	Operation of GNO ring	Operates smoothly without considerable backlash at 1.0 ~ 3.5kgcm.	
33	Effective time of the self-	8 ~ 14 sec.	
34	Self-timer setting force	Less than 450gcm at 15mm away from the pivot of the set lever.	
35	Assurance of the FM plate switch operation	Surely switch to the flashmatic setting at 1.5mm away from the upper surface of the shoe groove. Surely returns to the original position even when operated to the lower surface position.	
36	Effective time in the shutter manual	100% 80% b c f	Fully open cd+de+ef > 22mS bf < 37mS Minimum iris tcf = 16
37	Delay time	bc > 0mS	
38	Synchroniza- tion	 Insulation resistance: More than 30MΩ at 500V. Contact resistance: Conductive at DC 3V. 	
39	Accuracy of the distance scale graduation	+0.03 ^{±0.03mm} at ∞ +0.03 ^{±0.1 mm} at 1m	Check with the maximum aperture and on the optical axis.

No.	Item	Description	Remarks
40	Accuracy of RF coupling	+0.03 ^{±,0.0,7 mm}	Check with the maximum aperture and on the optical axis.
41	ES accuracy	Within the following range at ASA 100 BV 1 ~ 3	
42	ES accuracy (2)	The ASA sensitivity should be changed 0.5 - 1.5EV when the ASA ring is shifted one click-stop. K=1.3 Power supply voltage = 2.65 ±10.005	
43	Picture space	The center line of the picture space should not reach the perforation. Each space is 2.0 ±1.0 mm	
44	Accuracy of the flashmatic mechanism	See the separate sheet (6-VII-X30-X33).	
45	Minimum operation voltage	Operates normally at 1.8V.	
46	Current con- sumption	Less than 70mA at the static voltage of 2.8V.	
47	Current leakage	No leakage (less than 0.5uA)	·

LEE-17 DISASSEMBLY PROCEDURE

Disassembly Procedure of LEE17

Main Parts	Parts to be removed	Q'ty	Demountable Parts	Remarks
CC1006 (Base Plate)	PSK2x2.5SA	2	CC1006 (Base Plate) CC1012 (Cover B) CC1014 (Spring B)	Remove in order from the tripod screw.
CC1011 (Case B)				CC1006 (base plate) should be being re- moved. Although the case is bonded to the main body with Ever- stick, it can be re- moved by pulling strongly. See the Section of "Lubricants and Chemicals".
CB2160 (Upper Plate)	CA7399 (Lever Holder) CC1120 (R	1	CA8225 (Wind- up Lever) CA8231 (Wind- up Lever Base) CA7338 (Fric-	Some LEE 17 use two wind-up lever bases.
	Knob)		tion Spring) CA8025 (R Shaft) (R Knob Base)	·


Main Parts	Parts to be removed	Q'ty	Demountable Parts	Remarks
•	CA7559 (R Nut)	1		
	PUK2x3SA	2	CC1036 (Button)	
		or	NW6.1-392BO	
		1	CB2160 (Upper	
			Plate)	
CC1007	PUK1.7x2.5SO	1		
(Finder) (F	PUK1.7-308SO	1	CB2164 (F Base	This screw needn't be
Main Body)			Board)	removed, but only
				loosened.
	PSK2x4SO	3	CC1007 (Finder)	This finder is removed
<u> </u>			(F Main Body)	in a single body.
CC1081	PUX2x3SO	3	CC1081 (Guide	o CB2160 (upper plate)
(Guide Base		 	Base Plate)	should be being
Plate)			(guide plate,	removed.
·			gear 1 and wind-	o Tentative locking of
			up shaft in a	the wind-up lever
			single body)	before removing
			CC1080 (Gear 2)	CC1081 (guide base
				plate) is recommend-
			,	able for easy
				assembling.
CC1053	PUK2-240SO	1		CC1081 (guide base
(Wind-up				plate) should be being
Base Plate)		· · ·		removed.
	PSK2x2.5SO	2	CC1053 (Wind-	o Removed in wound-
			up Base Plate)	up condition.
				o CC1076 (cam plate)
				and CC1078 (S gear
				shaft) and others are


Main Parts	Parts to be removed	Q'ty	Demountable Parts	Remarks
				removed as a single body.
Shutter	CC1029 (Set Screw)	1	CC1028 (Set Lever)	
	CC1034 (Front Leather R)	1		Sufficient to peel off the extent equivalent to the base plate of the shutter.
	CC1035 (Front Leather L)	1		Same as above.
	PSK2x3SO	4	Shutter	o The scotch tape of upper plate, lower plate and CC1026 (L guide) should be being removed.
S40199 (Self-timer)	S40165 (VG Screw A)	1		o The base plate of the shutter should be being removed. o Though the earthing solder is coated, it can be removed by a plus screw-driver as it is.
	S40166 (VG Screw B)	1	S40199 (Self- timer)	
S40215 (Base Board A)	S40172 (E Ring)	4		o The self-timer should be being removed.

Main Parts	Parts to be removed	Q'ty	Demountable Parts	Remarks
	S40179 (C Ring)	1	S40215 (Base Board A) S40201 (Selector Lever) S40195 (Flywheel) S40182 (Coupling Gear) Take care, because the above parts tend to be disconnected.	The C ring is sometimes not removed due to the jamming of lead wires of CdS. In this case, the letter ring is recommendably removed. The lead wire of the magnet is very thin, so take care not to break it.
S40218 CdS	CA8095 (Letter Ring Holder)	1	S40206 (CdS Case)	S40205 (letter ring) and S40204 (ASA ring) and others are taken off as a single body.
	S40169 (Stopper Screw)	2	S40218 (CdS)	
CC1042 (Helicoid)	PUK1.4x2.2SO	3	CC1047 (Guide) CC1042 (Heli- coid) Demounted as a single body with the lens.	o S40206 (CdS case) should be being removed. o It is recommendable to mark the positions of CC1047 (guide) and CC1041 (front holder) before the removal of three PUK1.4x 2.2SO screws.


CC1046 (Mount Ring) (Demounted in a single body or The distance ring is with CC1045 RC1046 (Mount or CC1042 (helicoid) should be being removed.	Main Parts	Parts to be removed	Q'ty	Demountable Parts	Remarks
(distance ring)) counter-clockwise rotation.	(Mount		3	CC1046 (Mount Ring) (Demounted in a single body with CC1045	should be being removed. o The distance ring is demounted by the counter-clockwise

 $6 \sim W - C.1$





$6 \sim M - C.3'$



LEE-17

TROUBLESHOOTING

LEE-17 Troubleshooting

Contents

			F	Page
Ι.	Win	nding and Relateds		
	1.	Picture space reaches the perforation		28
	2.	Two-step release		29
	3.	Check lamp lighting upon the release lock		29
	4.	Excessive sprocket backlash		31
	5.	Double exposure prevention ineffective		32
	6.	Winding impossible	•	33
	7.	Insufficient wind-up lever pulling force		33
	8.	Insufficient hooking of the release plate lock to CB2168 (2-screw B)	•	34
II.	Ran	nge Finder and Relateds		
	1,	Adjustment of vertical displacement		35
	2.	Lateral ∞ displacement at infinity focusing		35
	3.	Defective coupling of the range finder		36
	4.	Range finder inoperative		37
III.	Len	as and Relateds		
	1.	Improper FC adjustment		38
IV.	Shu	tter and Relateds		
	1.	Shutter blade not open		38
	2.	Shutter blade left full open (both in AUTO and FM modes) .		42
	3.	Shutter blade full open in AITTO mode		44

		1 ag
	4.	Shutter blade full open in FM mode 45
	5.	Lamp not light
	6.	Slight displacement of B.C. lighting level 47
	7.	Low brightness EV defect 48
	8.	High brightness EV defect 48
	9.	Brightness EV defect in overall range 49
	10.	Synchro defective (not flash)
	11.	Synchro defective (not synchronize) 51
	12.	Synchro defective (over or under aperture opening) 52
٧.	Oth	ers
	1.	Self-timer mounting procedure and checking 53
	2.	Combination table of CdS cells and electric parts 54
	3.	Positioning of CC1045 (distance ring) 54
	4.	Mounting procedure of CC1049 (C screw) 55
	5.	Handling of CdS lead wires
	6.	Actual wiring diagram 56
	7.	Circuit diagram 56

I. Winding and Relateds

1. Picture space reaches the perforation

Cause	Remedy	Confirmation
1) Improper sprocket position	Adjust the sprocket position while watch the engagement of CA8245 (SP gear), CC1077 (S gear) and CC1080 (2 gear). The position of the sprocket tooth is made to be 12° - 36° as in the right illustration when the sprocket is pushed to the film rail, eliminating its backlash. In the troubleshooting, firstly remove CB2160 (upper plate) and CC1081 (guide base plate). CC1080 (2-Gear) CC1077 (S Gear) CC1073 (pawl) Caution: It is recommendable for easy assembly to remove the guide base plate with the winding lever tentatively locked.	Film Rail Surface Take care for the backlash of CC1077 (S gear). If it is excessive, adjust it with the pawl. See the Section of the pawl adjustment.

2. Two-step release

Cause	Remedy	Confirmation
1) Improper adjustment of CC1049 (C screw)	Remove CB2160 (upper plate), and adjust CC1049 (C screw) so that it becomes within the right indicated range. CC1049 (C Screw) CC1067 (3 Lever)	Wind-up release early (-) S release (0) +0.03 Wind-up release late (+) If there is considerable dump backlash with the 3-lever, the adjustment of the two-step release is difficult. See the "Dump backlash of 3-Lever" in the following.
2) Exces- sive back- lash of CC1067 (3-lever)	Adjust to have the backlash of less than 0.2mm at the point illustrated below with the lever caulked after tightening. CC1067 (3-Lever) CC1053 (Winding Base Plate)	The operation of the S lever is smooth without grating, and the backlash is less than 0.2mm.

3. Check lamp lighting upon the release lock

Cause	Remedy	Confirmation
1) Defor -	If the release button is strongly de-	(1) After the adjustment,
mation of	pressed before the winding, the	the winding operation is

Cause	Remedy	Confirmation
the lock	lock portion of the release plate is	sure, and the double
portion of	deformed and the space between the	winding prevention and
S40209	lock portion and CB2168 (2-screw	the returning prevention
(release	B) is enlarged, causing such	are assured.
plate)	trouble.	(2) When the shutter is
	When the deformation of the lock	released, the next wind-
	portion is not serious, rectify it,	ing is made possible
	but replace the release plate when	(allowance of 0.2mm re-
·	serious.	quired as in the left
		illustration).
		(3) Release is impossible
	Take the allowance	on the halfway winding.
	of approx. 0.2mm.	(4) Wind-up lock after S
		releasing is sure, and
		the checker lamp should
		not light upon the wind-up
	CB2168 (2-Screw B) S40209 (Release Plate)	lock.
:	Deformed as indicated by the dotted	(5) Allowance after S
	line. Rectify as indicated by the	releasing is more than
İ	actual line.	0.3mm.
2) Improper	CB2168 (2-screw B) is available in	
selection	the following three kinds. Select the	
of CB2168	proper one to have the above men-	
(2-screw	tioned allowance.	·
B)		
	No. H1 (H2)	(H ₂)
	1 3.2 (4.9)	H ₁
	2 3.4 (5.1)	
	3 3.6 (5.3)	
		<u> </u>

4. Excessive sprocket backlash

	y-	·
Cause	Remedy	Confirmation
1) Improper	Remove CB2160 (upper plate) and	(1) When the shutter is
adjustment	CC1081 (guide base plate), loosen	released, the 2-lever
of CC1073	CC1069 (pawl), and adjust by	should be disengaged
(pawl)	rotating CC1074 (5-collar) (eccen-	from the cam plate.
	tric). Adjust so that the backlash	(2) Backlash should be
	becomes less than 1/3 of the tooth	less than 1/3 of the tooth
	height. However, since CC1059 (2-	height as illustrated
	lever) would not be disengaged from	below.
	CC1076 (cam plate) if the backlash	
	is made zero, some extent of the	
	backlash is necessary.	
		Less than 1/3
	CC1059 (2-Lever)	of the tooth height
	CC1076 (Cam Plate) -CC1069 (Pawl Screw) CC1074 (5- Collar), Rotated to adjust the backlash.	
	Caution: The adjustment is to be	
	done in the condition of the 3-gear	•
	rotated and the 2-lever engaged in	
	the cam plate.	
	o The guide base plate is recomm-	
	endably removed with the winding	
`	lever tentatively locked previously	
	for the easy later assembling.	

Cause	Remedy	Confirmation
2) Peeling	Cement it again to CA8244 (sprocket)	(1) The cementing should
off of	or replace the sprocket (the sprock-	be done with beveled side
CA8248	et comes as a set with the clutch	up.
(clutch	plate). The cementing is done by	(2) No adhesive should
plate)	Araldite with the beveled side of the	come out of the fitting
	clutch plate facing up.	portion of the clutch and
	CA8248 (Clutch Plate)	the sprocket shaft.
	(0 (0)	(3) Should be cemented on
	GA 9244 (Samookot)	the position indicated in
	CA8244 (Sprocket)	the left illustration with
	Araldite	no floating.

5. Double exposure prevention ineffective

Cause	Remedy	Confirmation
1) Disen- gagement of CC1072 (4-spring)	Hook the 4-spring as illustrated. Bond CC1070 stopper side with adhesive. Bond the point of the spring with adhesive. CC1072 (4-S	pring)
	CC1070 (Stor	oper)
2) Disen- gagement of CC1066 (3-spring)	Hook the 3-spring with the longer half engaging with CC1067 (3-lever) as illustrated below. CC1066 (3-Spring with the longer (3-Lever)	1

Cause	Remedy	Confirmation
3) Disen-	Hook the 2-spring with the longer	
gagement	half engaging with CC1059 (2-lever)	
of CC1062	as illustrated below.	
(2-spring)	CC1062 (2-Spring) CC1059 (2-Lever)	

6. Winding impossible

Cause	Remedy	Confirmation
1) Disen-	Hook the 1-spring with the longer	
gagement	half engaging with CC1054 (A lever)	
of CC1057	as illustrated below.	
(1-spring)		
	CC1057 (1-Sp CC1054 (A Lever)	ring)

7. Insufficient wind-up lever pulling force

Cause	Remedy	Confirmation
1) Deforma- tion of	Remove the upper plate and CC1081 (guide base plate), and disconnect	Friction ring is not discriminative in the front

Cause	Remedy	Confirmation
CA8255	CA8242 (1-gear shaft), and replace	and back.
(friction	CA8255 (friction ring) or rectify it.	2) The 1-gear base is
ring)	CC1081 (Guide Base Plate)	applied with the loose side up.
,	CA8227 (Winding Shaft)	3) Coat the Rocol Paste on the friction ring contact
	CA8255 (Friction Ring)	area of the winding shaft and the winding plate
	CA8233 (1-Gear Base)	contact area. 4) The tightening of the
••	CA8242 (1-Gear Shaft)	1-gear shaft is assured without floating and loose-ness (tightening torque is more than 2.5kgcm).
• • •		

8. Insufficient hooking of the release plate lock to CB2168 (2-Screw B) $\,$

Cause	Remedy	Confirmation
1) Incorrect	After removing the upper plate and	
position of	CC1081 (guide base plate), loosen	
CC1053	two PUK2x2.5SO and one PUK2-	·
(winding	240SO and apply the winding base	
base plate)	plate forward as in the illustration	
	below and tighten again the above	
	screws.	
S4	0209 Release Plate	
CE	32168 (2-Screw B)	
	Applying dire	ction
	CC1053 (Wind	
	CC1001 (Main Body)	

II. Range Finder and Relateds

1. Adjustment of vertical displacement

Cause	Remedy	Confirmation
1) Incorrect angle of LC4075 (2-mirror) due to improper adjustment of CB2172 (mirror screw)	With the cement of the mirror and lens not peeled off, if the reflected image is as follows with respect to the transmitted image when viewed through the collimator: The reflected image is displaced upward: Turn the mirror screw clockwise . The reflected image is displaced downward: Turn the mirror screw counter-clockwise .	(1) Vertical image displacement should be less than 1'30" when measured by a collimator of f=600mm. (2) The images should not be displaced when the distance ring is rotated 2 - 3 times and strongly or quietly struck against the stopper, after the images have been super-
	LC4075 (2-Mirror) CB2172 (Mirror Screw	imposed once. (3) Should be within the rating at ∞ and 1m. If excess image displacement occurs at either of the above distances, adjust the mirror screw so as to satisfy the rating at each distance.

2. Lateral displacement at infinity

Cause	Remedy	Confirmation
1) Displace-	Open CC1113 (rear cover), re-	(1) The lateral image
ment due	move CA8106 (hole screw) and	displacement should be
to improp-	adjust by rotating the AD screw	less than 1' when the
er adjust-	with the screwdriver No. 3.	collimator of f=600mm
ment of	When viewing through the collimator	is used.
_		

Cause	Remedy	Confirmation
CA8103	if the reflected image is as follows	(2) If the rotary force of
(AD screw)	against the transmitted image:	the AD screw is excessively light, replace or
	Displaced leftward: Turn the AD screw counter-clockwise .	remedy the 1 lever. (3) The images should not
Displaced rightward: Turn the AD screw clockwise (CA8103 (AD Screw)	be displaced when the distance ring is rotated 2 ~ 3 times and strongly or quietly set to focus at ∞ after the images have been matched once.	

3. Defective coupling of the range finder

Cause	Remedy	Confirmation
1) Improper adjustment of coupling pin		 (1) Distance scale accuracy at ∞: +0.03 mm at 1m: +0.03 mm (2) RF coupling accuracy: +0.03 mm (3) If the rotary force of the coupling pin is abnormally light. caulk it once more.
·	···	<u> </u>

Cause	Remedy	Confirmation
	4. Adjustment lateral displacement	
	at infinity focus as described in	
	the preceding procedure.	
	5. Repeat the procedures 1 - 4, and	
	adjust the lateral displacement at	
	the close distance of 1m.	
	GN Th. 15 GN Th. 15 Coupling Pin	

4. Range finder inoperative

Cause	Remedy	Confirmation
1) Squeak	Cosmolbrick is applied to the	Even when the distance
of CB2171	sliding portion of the F main body	ring is violently moved,
(mirror	(CC1007) and the mirror base.	the range finder follows
base)	When there is squeaking due to the	correctly and quietly.
	lubricant shortage or foreign matter	
	intrusion, demount the mirror base	
·	and apply thin coat of cosmolbrick to	
	the sliding portion after cleaning it.	
	Caution: For the mirror base de-	
	mounting. do it after marking the	
	mirror base position.	

III. Lens and Relateds

1. Improper FC adjustment

Cause	Remedy	Confirmation
1) Incorrect position of CC1047 (Guide)	Do the FC adjustment by shifting the guide held onto the lens barrel (CC1039). FC adjustment procedure (1) Remove the letter ring holder (CA8095) and CdS holder (S40206). (2) For full opening of the sector, take off the lead wire soldered to the base board (B S40216) (removing either one of the wires will be sufficient). (3) Set the distance ring to the position, and loosen three PUK1.4x2SO fixing the guide plate. (4) While depressing the shutter button, adjust so that the tolerance is within +0.03 at page 1.	CC1047 Coma Plate
	<u>L</u>	

IV. Shutter and Relateds

1. Shutter blade not open

Cause	Remedy	Confirmation
1) Wire	When the voltage of 2.65V is applied	If the current flows at
breakage	by the use of a constant voltage	about 65mA or 30mA (with
and short-	power supply (DC), the current	no lamp) when the shutter
circuit of	flows at about 65mA if normal and	is released, the electric

Cause	Remedy	Confirmation
the electric parts	Range of a tester 20mA DC or more	parts are normal.
2) MG cord breakage	The cord is broken if the pointer needle does not deflect when measuring as follow with the use of a tester. In this case, replace the MG (magnet) and adjust the position.	(1) If the MG is normal, the resistance value is approximately $60^{\pm 10}$ Ω (2) The shutter blade should operate normally at 2.0V. (3) Confirm the EV value.

Cause	Remedy	Confirmation
3) Defective soldering of electric parts		(1) The shutter blade should operate normally at 2.0V. (2) Check EV.
4) Contact failure of S ₁ contact piece	In case of the contact failure of the contact piece, correct the contact piece height to about the groove position of the post. Post Contact Piece Groove	If the contact piece is too high, the defect of "heavy release plate returning" may be caused.
5) Incorrect MG position	If the voltage at both ends of the MG are stable at 1.4V when the release plate is depressed, the MG position is incorrect (the battery voltage is 2.65V). [MG Position Adjustment] 1. Connect the DC constant voltage power supply to the battery cord. 2. Gradually shift the MG in the arrow mark direction to find the best position so that the sector operates normally at 2.0V.	(1) The sector should operate normally at 2.0V.

Cause	Remedy	Confirmation
	3. Tighten the MG fixing screw to fix the MG.4. After fixing the MG, confirm that the sector operates normally.MG Fixing Screw	
	Adjusting Direction	·
6) Contact	If the contact piece S ₃ is separated	
failure of	from the leaf spring before releas-	
S_3 contact	ing, adjust the contact piece with a	
piece	pincette.	
	1. Adjust the contact piece so that	
	the leaf spring is tensioned with	
	approx. 0.2mm bend when the con-	
	tact piece is contacted to the leaf	
	spring. 2. Confirm that the space between	•
	the contact piece and the leaf spring	·
	is approximately 0.5mm upon	
	releasing.	
Lear	S Contact Piece 0.2 Spring Contact Piece	
	<u> </u>	

Cause	Remedy	Confirmation
7) Excessive contact resistance of S ₃ contact piece	Remedy When the resistance at the both ends of C are more than 1 n in the condition prior to releasing: 1. Insufficient contact pressure (insufficient leaf spring tension) ⇒ Adjust the contact piece and the contact leaf. 2. Fouled contact surface ⇒ Clean the contact piece and the leaf spring with mixed solution, and adjust them.	Normal if the resistance value is less than 10 at the both ends of the condenser.
8) Defective soldering of electric parts	If the tester needle does not deflect in the above checking (7), check the following parts. 1. S ₃ Contact Piece 2. S ₃ Leaf Spring 3. Condenser (C) Check the soldering	

2. Shutter blade left full open (both on AUTO and FM)

Cause	Remedy	Confirmation
1) Contact failure of	Insufficient spring pressure of AF contact pieces (S ₄ contact piece)	(1) Normal if the resistance values between A and the
S_4 contact	and the fouled contact surface.	common and between F
piece	1. Insufficient contact piece pressure	and the common are $ eq 0 \Omega$.

Cause	Remedy	Confirmation
	Wipe the left illustrated contact surface with mixed solution.	the tester.
2) Defective operation of S40184 (control lever)	The control lever disengages from the release plate and holds the driving cam. ⇒ Confirm the release plate deflection, and then rectify the control lever spring shape.	 (1) The shutter blade should operate normally at 2.0V. (2) The operation is normal when the control lever is pushed by the release

Cause	Remedy		Confirmation
	S40209 (Release S40184 (Control Lever) S40185 (Cont		plate in the released condition and shifted to the position B.
3) Defective soldering of electric parts	 Shortcircuited S₃ soldering Shortcircuited (+) and (-) lines of condenser (C) Broken pattern between S₄ (common) and R 	Solder again correctly	 The shutter blade should operate normally at 2.0V. Check EV. Check FM.

3. Shutter blade full open in AUTO mode

Cause	Remedy	Confirmation
1) Contact failure of S ₄	This sometimes occures only in the AUTO mode because of the curved and fouled print board, so check the following points. 1. Insufficient contact piece pressure 2. Fouled contact surface	See the Item 2-1 on page 42.
2) Defective soldering of electric parts	 Defective VR terminal soldering. Defective soldering of the CdS cell cord. Broken pattern between: 	 The shutter blade should operate at 2.0V. Check EV.

Cause	Remedy		Confirmation
	CdS cell cord (white or blace) VR, S ₄ VR ⇒ Solder again or replace	,	
3) Defective soldering of CdS	1. Broken CdS base board pattern 2. Defective CdS soldering 3. Internal CdS cord breakage 4. Shortcircuit between the CdS cell cord (white or black) and the CdS cell post 5. Shortcircuited CdS cell cord (white or black) and R ₁	Solder again or replace the CdS	The CdS cord breakage is very few, so its replacement should be done only when the defective part cannot be found elsewhere. For the replacement, check the matching of the colored code previously.

4. Shutter blade full open in FM mode

Cause	Remedy	Confirmation
1) Contact	This sometimes occurs only in the	See the Item 2-1 on page 42.
failure of	FM mode because of the curved	
S 4.	and fouled print board, so check	
	the following points.	·
	1. Insufficient contact piece	
	pressure	
	2. Fouled contact surface	
2) Defective	Defective and broken soldering of	1) The shutter blade should
soldering	the resistor ${ m R_{5^{\circ}}}$ causes the same	operate normally at 2.0V.
of electric	trouble.	2) Check EV and FM after
parts	\Longrightarrow Solder again for the resistor R_{5}	the repair.
	or replace it.	

5. Lamp not light

Cause	Remedy	Confirmation
1) Cord breakage of S40174 (micro- lamp)	If the pointer needle does not deflect when tester probes are applied to both ends of the lamp cords as illustrated below, replace the lamp.	If the lamp is normal, the tester needle points approximately 60.0 and the lamp lights.
·	Tester 1 Range	
2) Micro- lamp cord breakage	Check if the cord is broken at the lamp root, and if so, replace the lamp.	
3) Defective soldering of electric parts	The lamp does not light also if the soldering of the following parts are defective. 1. Lamp Cord 2. Battery Cord (+) Red Battery Cord (-) Blue 3. R; Cord 4. R; Cord 5. T; Cord	·

Cause	Remedy	Confirmation
4) Contact failure of S ₆ contact piece	S ₆ contact piece and the leaf spring are not contacted in the condition prior to releasing. Bend the leaf spring with a pincette to make their contact. Before the adjustment, be sure to clean the both pieces with mixed solution. S Contact Pieces Leaf Spring	 S₆ contact piece should contact to the leaf spring prior to the releasing, and the leaf spring should be bent by approximately 0.2mm. The contact piece and the leaf spring should be separated by approximately 0.5mm after the sector is closed with the release plate being depressed.

6. Slight deviation of B.C. lighting level

Cause	Remedy	Confirmation
1) Lamp lights even at 1.8V	 (1) Replace R₇ (110 Ω) by a 100 Ω one. (Replace R₇ by a resistor with the dimensions applicable to the printed board.) (2) If the above measure is not successful. connect the R₇, back again and replace the transistor T₃. 	B.C. Level: 2.0 + 0.25 V
2) Check lamp does not light at 2.25V.	 Replace the B.C. lamp. Replace R₈ (200 Ω) by a 180 Ω resistor. If the above measures are unsucessful, return the R₈, and replace the transistor T₃. 	

7. Low brightness EV defect

Cause	Remedy	Confirmation
1) Defective CdS	When the resistance value of BV 8 is considerably deviated from the following value, replace by a CdS	EV accuracy at ASA100 is: BV 1 ~ 3: ±1.3EV (tentative)
	of the same colored code. Green (G): 37.5 - 49.3K \Omega Red (R): 22.4 - 37.4K \Omega Blue (B): 14.9 - 22.3K \Omega Adjust the EV after the replacement	Colored Code Printed Board B

8. High brightness EV defect

Cause	Remedy	Confirmation
1) Defective soldering of electric parts	When the V_R soldering is defective, the high EV becomes excessive. \Longrightarrow Solder again.	EV accuracy at ASA100 is: BV 8 - 14: ±1.0EV BV 15 - 17: ±1.2EV BV 17: ±1.2EV (tentative)
2) Improper adjustment of V _R	The V _R adjustment causes some change in the low brightness side, but mainly relates to the high brightness side. Contact Piece When the contact piece is rotated: (1) in the A direction: EV becomes under (2) in the B direction: EV becomes over	(1) The shutter blade should operate normally at 2.0V. (2) EV accuracy at ASA100: BV 8 ~ 14: ±1.0EV BV 15 ~ 16: ±1.2EV BV 17: ±1.2EV (tentative)

Cause	Remedy	Confirmation
3) Incorrect	If the position of S40182 (coupling	
position of	gear) is incorrect in the assembling	
S40182	after the shutter disassembly, the	
(coupling	high brightness becomes under.	
gear)	(Since the flywheel (S40195) actuates	
	at the start of the sector operation,	
	if wrongly positioned, the sector	
	is delayed in action and opened not	
ı	fully at high shutter speed.)	
	S40182 (Coupling Gear) Shift the position of the flywheel and the coupling gear tooth to make the clearance in the upper and lower sides.	

9. Brightness EV defect in overall range

Cause	Remedy	Confirmation
1) Improper	When each EV is under or over,	
adjustment	adjust by increasing or decreasing	
of S4 0221	the filter of the CdS cell.	
(filter)		·

Cause	Remedy	Confirmation		
	1. Each EV under: Increase the			
	filter.			
	2. Each EV over: Decrease the			
	filter.			
	Filter S40206 (CdS Ca Scotch Tape S40218 (CdS)	se)		
	S40221 (Filter)			

10. Synchro defective (not flash)

Cause	Remedy	Confirmation				
Cause 1) Contact failure of SY contact piece	Remedy 1. If the contact points are not closed even when the shutter blade is fully opened. correct the leaf spring with a pincette. See the step 11 "Synchro defective (not synchronize)" for the correction procedure. 2. Fouled contact surface	Confirmation 1. Contact Resistance Conductive at DC 3V 2. Contact Efficiency More than 60% at 2.5ms, More than 80% at 6ms 3. Insulation Resistance More than 30M \(\Omega \) at 500V.				
	Wipe the contact surface of the contact piece and the leaf spring with mixed solution, and readjust the leaf spring.					

Cause	Remedy	Confirmation			
2) Cord	1. Defective grounding				
breakage '	Should be surely grounded to the				
	S base plate.				
	2. Each lead wire should be surely				
	soldered.				
	See the disassembly drawing Fig.				
	4/4.				

11. Synchro defective (not synchronize)

Cause	Remedy	Confirmation		
1) Improper adjustment of SY contact piece	With the shutter removed, adjust the SY contact piece as follow. Correct the leaf spring with a pincette so that the contact piece is contacted to the leaf spring when the aperture is more than 80% (approx. 8.5ϕ) of the maximum aperture (10.61ϕ) .			
	Leaf Spring Contact Piece	100% d e f f		


Cause	Remedy	Confirmation
1) Improper adjustment of GN ring	Adjust the slitting of the GN ring receiver contacting to the cam of the GN ring (S40212).	See the Item 6-VII-X30-X33.
receiver	Enlarging the slitting: Iris dia- phragm narrowed Narrowing the slitting: Iris dia- phragm enlarged	
	GN Ring Receiver Slit	GN Ring)
		-
		·

V. Others

1. Self-timer (VG) mounting procedure and Checking

When the self-timer is abnormally stopped or any other trouble occurs, replace the whole VG unit.

- a. VG mounting procedure
 - 1) Fit the VG set lever shaft into the receiving hole of the base plate, and fit the two holes of the VG unit onto the tip of the posts of the base plate and engage the two units. In this case, take care not to touch the $\rm S_3$ and $\rm S_6$ leaf springs.
 - 2) Fix the VG unit on the base plate with the VG mounting screws (two pieces).



b. Checking of VG

- 1) Connect the power of DC 2.65V to the shutter, and set the self-timer to the predetermined angle.
- 2) Release the shutter by means of the release plate, and check the delay time. $(10.0^{\pm 3} \text{ sec.})$
- 3) Check the release plate holding time. (1.0 sec. or more)
- 4) Check the release position. (6.0 $^{\pm03}$ sec. from the stop position)
- 5) Check the timing of the release lock and the self-release.

 (The release lock is earlier than the release timing.)


2. Combination of CdS cells and electric parts

a. Table of Electric Parts Combination

Class	Color- code	CdS Resistance (BV 8) (Ka)	C (uF)	R ₁ (Ω)	R ₂ (ΚΩ)	R ₅ (ΚΩ)	V _R (Ko.)	Disas- sembly Drawing Mark
1	Green	37.5-41.1-49.3	15	30	30~51	43	5	G
2	Red	22.4-28.0-37.4	22	11	11	30	11	R
3	Blue	14.9-18.7-22.3	33	11	11	20	11	В

b. Position of color-code

The color-code is provided at the lower illustrated position of S40215 (printed board) and S40216 (base board B). In the replacement, be sure to use the one which has the same color-code.




3. Positioning of CC1045 (distance ring)

Screw CC1046 (mount ring) into CC1046 (distance ring) fully, and return it to the distance scale position.

4. Mounting procedure of CC1049 (C screw)

- 1) Magnetize the screwdriver No.5, put the C screw on the screwdriver and apply it to the threaded hole provided on the release plate.
- 2) Turn the screw in the counterclockwise direction with the screwdriver No.1 or 2 from the above of the hole for tightening it.


See the Item 6-VII-D4 for the adjustment of the screw.




5. Handling of CdS lead wires

If the CdS lead wires are inserted in a wrong manner, the helicoid may get stuck (at ∞ or closet distance), so handle the lead wires properly as follow.

- 1) Insert the black (or white) lead wire first into the lead wire channel of S40206 (CdS case), and then the orange lead wire.
- 2) Twist the lead wires two times, and house them in CC1046 (mount ring) while folding them into two using a screwdriver as illustrated below.



6. Actual Wiring Diagram



7. Circuit Diagram









PHOTO LUB 023P
















Apply to the periphery as far as possible taking care not to touch the Everstick to the C ring.

























Stick with the backlash portion put aside in the arrow mark direction.





Bond the clutch plate with the beveled side up.